Maintenance of existing Borewells in Ward no. 05

Work code. 005-19-000040

Est cost Rs. 30.00 Lakhs.

Work order no. - BBMP/EE/BTP/WO/50/2019-20

Name of Contractor - Sri B Girish
Jayanagara
Bangalore. 560011

01/07/19

| Date | S.L.NO | Motor HP | MATerials | Pipe | Thriding Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 01/07/19 | 01 | 15 HP | Motor winding<br>Motor bush<br>Bering set<br>Contact blade<br>Pravender<br>NRV - 1<br>Union - 1<br>X NIPPle - 3<br>Ellow - 2 | 44 | 28 | Srinivas pura Hemanna Temple Near | |
| 03/07/19 | 02 | 12.5HP | Motor winding<br>Motor Bush<br>Bering set<br>Carbon ~~bush~~ housing<br>PUMP<br>Steele bush - 30<br>Implier - 20<br>PUMP bowler - 10<br>Rotor = | 36 | | Dwarakanagar 3rd cross | |
| 7/07/19 | 03 | 7.5 HP | Motor winding<br>Motor Bush<br>PUMP<br>Implera - 10<br>bush - 20<br>Bering set | Rodl PIPE | | Noor Nagar Main Road Car wash, Near. | |
| 12/07/19 | 04 | 15.HP | Motor winding<br>Motor Bush<br>bering set<br>Stater<br>Relley<br>Plevender<br>NRV | 66 | | Kattigenahalli Muneshwar Layout | |

| Date | SL.NO | HP | Materials | Pipe | Threading Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 15/07/19 | 05 | 17.5HP | Motor winding<br>Motor Bush<br>Bearing set<br>Stater .<br>Contact blade<br>Plevender<br>Relay<br>NRV – 1<br>Union – 1<br>X-NIPPle – 03<br>Ellow – 2 | 58 | 110 | Babanagar 52V Appartment | |
| 18/07/19 | 06 | 17.5HP | Motor winding<br>Bush<br>Stater<br>Plaverder<br>Relay<br>NRV – 01<br>3 ·Caler<br>X NIPPle = 03 | 48 | | Kattigenahalli Sapthagiri Layout | |
| 20/07/19 | 07 | 17.5HP | Motor winding<br>Bush<br>· Bearing Set<br>PUMP .<br>Emplem – 10<br>Boulen – 05<br>Bush – 20<br>·NRV – 01<br>X NIPPle = 03<br>Elbow = 2<br>Rofer – 1 | 50 | | Dwarakanagar Bala Ji Layout | |

Thursday

| Date | SL.NO | HP | Materiales | Pipe | Pipe | Place | Signature |
|---|---|---|---|---|---|---|---|
| 21/07/19 | 08 | 12.5HP | Motor winding<br>bearing set<br>bush<br>NRV-01<br>X Nipple = 03<br>Elbow = 2 | 40 |  | Agrahara Layout 12 th cross |  |
| 23/07/19 | 09 | 12.5HP | Motor winding<br>Bush<br>Stater<br>Relay<br>Plevender<br>Test bearing.<br>NRV-01<br>Reder. 1 | 35 |  | Thirumenahalli Main Road. |  |
| 24/07/19 | 10 | 15HP | Motor winding<br>bearing set<br>Carbon Houseing<br>NRV .Union 01<br>Elbow -02<br>X NIPPle - 02 | 54 |  | Bubanagar . |  |
| 26/07/19 | 11 | 12.5HP | Motor winding<br>Test bearing.<br>PUMP EMpler - 20<br>Gun Metal bush - 30<br>Stall bush - 30<br>Guide on - 30 | 35 |  | Kogilu 4th cross |  |
| 27/07/19 | 12 | 12.5HP | Motor winding<br>Bush<br>.Stater<br>Realay<br>Prevender. | 37 |  | Datta Layout 1st cross |  |

| Date | SL.NO | HP | Materailes | Pipe | Thrading<br>PIPE | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 28/07/19 | 13 | 7.5HP. | Moter winding<br>Test bearing<br>Bush<br>Stater<br>Reley<br>Revender | 12 | | Bellahalli cross Main Road. | |
| 29/07/19 | 14 | 175HP | Moter winding<br>bearing Set<br>Bush.<br>NRV –<br>Union. | 49 | | Siri Nagar, 2nd cross | |
| 30/07/19 | 15 | 15HP | Moter winding<br>Bush.<br>Stater<br>Reley<br>Union.<br>NRV.<br>X NIPPle | 45 | 90 | Defancey Colony. | |
| 31/07/19 | 16 | 15HP | Motor winding<br>Bush<br>Test bearing Set<br>Stater Reley<br>Drevender<br>Union. X NIPPle<br>Roder – 1 | 45 | | Balaji layout (Basavalingappa | |

01/08/2019

| Date | SL.NO | HP | Materials | Pipe | Thrading<br>Pipe | Place | Signature |
|---|---|---|---|---|---|---|---|
| 2/08/19 | 01 | 15 HP | Motor winding<br>Test bearing set<br>Bush<br>Roler - 1 | 45 | 90 | Dwarakanagar 1st Main . | |
| 4/08/19 | 02 | 10 HP | Moter winding<br>Bush<br>Test bearing set<br>Stater<br>Relay<br>Revender | 22 | | Chokkanahalli (gundu Thoppu) | |
| 5/08/19 | 03 | 15 HP | Moter winding<br>Test Bearing Set<br>Carbon Houseing .<br>PUMP .<br>Empelerd = 04<br>Bush = 20<br>Union = 01<br>NRV = 01<br>X Nipple = 03 | 48 | | Agrahara Lay out 1st Main<br>11th cross | |
| 7/08/19 | 04 | 15HP | Moter winding .<br>Bush<br>Bearing Set<br>Stater .<br>Stater Relay<br>Prevender<br>NRV - 01<br>Union = 1<br>X Nipple = 03 | 50 | - | Balaji Lay out 2nd cross<br>Agrahara lay out - | |

| Date | SL.NO | HP | Materailed | Pipe | Threading Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 9/08/19 | 05 | 17.5HP | Motor winding<br>bearing set<br>bush<br>Carbon Hoshery<br>Pump Stall bush = 30<br>Emplend. - 20<br>Pump bowled. = 10<br>Roter , | 45 | | Palanahalli kaliyaram | |
| 11/08/19 | 06 | 7.5HP | Motor winding<br>bush<br>NRV - 1<br>Union - 1<br>X Nipple = 03<br>Elbow = 02<br>Stater<br>Relay<br>Prevender | 08 | | Agrahara Chamundi layout | |
| 13/08/19 | 07 | 17.5HP | Motor winding<br>bearing set<br>bush<br>Pump<br>Implyerd - 10<br>Stall bush - 30<br>Bowl - 05<br>NRV = 1<br>Union = 1<br>Elbow = 02<br>X Nipple = 3<br>Roter - 1 | 48 | | Ansandri layout (kalligenahalli) | |

| Date | SL NO | HP | Materialed | Pipe | Threading<br>Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 16/08/19 | 08 | 15HP | Motor winding<br>Bush<br>Bearing set<br>Stater<br>Plevender<br>Relay<br>NRV - 1<br>Callerd - 03<br>Rocker | 44 | | Srinivaspura SMRShaka Road | |
| 17/08/19 | 09 | 15HP | Motor winding<br>Bush<br>Bearing set<br>PUMP<br>Mplyd - 10<br>Bowler - 05<br>Stell bush - 05<br>Gun Metal bush - 25<br>NRV - 01<br>Union - 01 | 40 | | Agraharapaly out 7th cross | |
| 20/8/19 | 10 | 17.5HP | Motor winding<br>bush<br>Tealt bearing set<br>Stater<br>Relay<br>Plevender<br>Bowlord - 5<br>bush = 10<br>NRV - 1<br>Union = 01<br>Callerd = 03<br>Rocker - 1 | 42 | 84 | Vinayakanagara 1st main | |

|  |  |  |  |  | Threading |  |  |
|---|---|---|---|---|---|---|---|
| Date | SL NO | HP | Materials | Pipe | Pipe | Place | Signature |
| 21/08/19 | 11 | 10HP | Motor winding<br>bush<br>Stater<br>Relay<br>Plevender<br>Caller – 03<br>Union – 1<br>NRV – 1<br>Rocker | 25 |  | Huneshwer Temple (kattigenahalli |  |
| 22/08/19 | 12 | 15 HP | Motor winding<br>bearing set<br>bush<br>PUMP<br>Emplend – 10<br>Stell bush = 30<br>Elowerd = 5<br>NRV = 01<br>union = 01<br>X nipple = 03 | 110 |  | Dwarakanagara Over Tank |  |
| 24/08/19 | 13 | 17.5HP | Motor winding<br>bush<br>NRV – union – X nipple = 02<br>Elbow = 02<br>Stater Relay<br>Rocker | 147 | 94 | Vinayakanagar Rama Temple Back Said |  |
| 25/08/19 | 14 | 15HP | Motor winding<br>Bearing set<br>bush<br>Pump Bush = 25<br>Sleve = 30<br>Emplend = 10<br>NRV = union = | 110 |  | Balaji lay out (Agraharalayout) |  |

|  |  |  |  |  | Thredin |  |  |
|---|---|---|---|---|---|---|---|
| Date | Sl.No | HP | Materials | Pipe | Pipe | Place | Singnature |
| 27/08/19 | 15 | 17.5 HP | Motor winding<br>base<br>bearing set<br>Stator Relay<br>Plevender . PUMP .<br>BUSH = 20<br>Selve = 20<br>Emplex = 10<br>X nipple = 02<br>Union , NRV, | 48 |  | Sri RaM pura |  |
| 28/08/19 | 16 | 15 HP . | Motor winding .<br>Test bering set<br>NRV . Union , Cellord-03<br>Roler . | 64 |  | Agrahara Layout 9th cross |  |

01/09/2019
c

third

| Date | SL.NO | HP | Materialen | Pipe | Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 01/09/19 | 01 | 17.5 HP. | Motor winding.<br>Motor bush<br>Tesh bearing set<br>Union . NRV-01<br>Caller = 03<br>Stator Reeling.<br>Revender.<br>Rotor | 50 | | Sri Rampura Muneshwara Temple Near. | |
| 03/09/19 | 02 | 15 HP. | Motor winding<br>bush<br>Pump bush - 25<br>Sleeve = 25<br>Empleen = 10<br>Union . NRV-1<br>Stator . Reeling<br>Rotor - | 40 | | Agrahara layout 8th cross. | |
| 06/09/19 | 03 | 12.5HP | Motor wind<br>bering set<br>bush<br>Pump . bush - 30<br>Sleeve = 30<br>Gradwen = 30<br>Empleen = 16<br>Caller = 03<br>Soft = 01 | 35 | | Agrahara layout 1st main 15th cross | |
| 7/09/19 | 04 | 12.5HP | Motor winding<br>bush<br>Test Bering. Set<br>caller=03<br>Union . NRV. 1<br>X NIPPLE = 03 | 35 | | Vinayakanagara Ist Main. | |

| Date | SL NO | HP | Materialer | PIPe | Thriding PiPe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 8/09/19 | 05 | 12.5HP | Motor winding<br>bose<br>Test berny set<br>Stater Relay<br>Rlevender.<br>contact<br>NRV. union.<br>x NIPPle = 03<br>Culler = 02<br>Rater. | 50 | 100 | Masadi Road kaltigenahalli | |
| 9/09/19 | 06 | 15HP | Motor winding.<br>buke<br>bearing set<br>Stater Relay<br>NRV- 1<br>Union - 1<br>x NIPPle = 03<br>Elbow = 02 | 40 | | Agrahara lay out Aganavadi School Near | |
| 11/09/19 | 07 | 15HP | Motor winding<br>buse<br>Bearing set<br>Carbon housing<br>PUMP<br>Stell bush - 30<br>EMPlem - 20<br>Allen Sely = 4<br>PUMP blower = 10<br>Union - 1<br>NRV - 1<br>X NIPPle = 02<br>Rater | 42 | 84 | Srinivasapura Hemanna TEMPle Near | |

|  |  |  |  |  | Threding |  |  |
|---|---|---|---|---|---|---|---|
| Date | SL. NO | HP | Materialer | Pipe | Pipe | Place | Singnature |
| 14/09/19 | 08 | 12.5HP | Motor winding<br>bearing set<br>bute<br>Stater Relay<br>Rlevender.<br>PUMP bute - 20<br>Empler = 10<br>Hell bute = 12<br>NRV = 1 | 35 |  | kuttiyenahalli over Tank near. |  |
| 15/09/19 | 09 | 7.5HP | Motor winding.<br>bute<br>bearing set<br>NRV. union.<br>X NIPPle = 03<br>Caller = 02<br>Stater Relay<br>Rlevender<br>Roter | 15 |  | Palamahalli Thoda |  |
| 17/09/19 | 10 | 15 HP | Motor winding<br>bute<br>bearing set<br>PUMP bute - 20<br>Salve - 20<br>Empler - 10<br>Caller = 5<br>NRV = 1<br>Union = 1<br>Roter - | 48 | 96 | Ambedkar Nagar. |  |

| Date | SL.NO | HP | Materials | Pipe | Threading Pipe | Place | Signature |
|---|---|---|---|---|---|---|---|
| 18/09/19 | 11 | 15HP | Motor winding<br>bute<br>· Stater Relay<br>Plevender NRV-1<br>union,<br>Caller . X·NIPPle<br>Roter , | 40 |  | Chokkanahalli Lay out | ✓ |
| 21/09/19 | 12 | 12.5HP | Motor winding<br>bearing set<br>PUMP Bush = 20<br>sleeve = 20<br>Gadi venu − 15<br>EMPlend = 05<br>NRV- 1 | 38 |  | Kogale Lay out | ✓ |
| 22/09/19 | 13 | 15HP . | Motor winding<br>bearing set<br>buse<br>Stater Relay<br>Plevender<br>bell kle − 3 site .<br>Caller = 03<br>NRV-1 union-1<br>X NIPPle = 02 | 45 | 90 | TIPPU nagar . | ✓ |
| 24/09/19 | 14 | 15HP | Motor winding<br>bute<br>union . NRV . X NIPPle=03<br>Caller=02 Elbow=02<br>Stuter Relay<br>Plevender .<br>Roter ⌐ | 45 |  | DMK Lay out |  |

| Date | SL.NO | HP | Materialel | PIPe | Thirding<br>PIPe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 26/09/19 | 15 | 15 HP. | Motor winding<br>bearing set<br>fuse<br>Starter Plevender<br>NRV - 1 union - 1<br>X nipple - 02<br>PUMP. Sleve = 10<br>Stell bush = 20<br>Rober - | 45 |  | Chamundieshwari lay out<br>Kalligenahalli |  |
| 28/09/19 | 16 | 15HP. | Motore winding.<br>Rodor.<br>bearing set<br>NRV 1<br>X NIPPle<br>PUMP Sleve. | 43 | 86 | Palurahalli TO Vinayakanagar<br>Road |  |

1/10/19

| Date | Sl.NO | HP | Materials | Pipe | Threading Pipe | Place | Signature |
|---|---|---|---|---|---|---|---|
| 2/10/19 | 01 | 15·HP | Motor winding<br>base<br>bearing set<br>Pump sleeve<br>base - 10<br>Empleard . 05<br>Union ,<br>Callord | 44 |  | Srinivas Pura Hemmana Temple Near |  |
| 4/10/19 | 02 | 12.5HP | Motor winding<br>base<br>Carbon Macheng.<br>Stator , Reeling .<br>privender<br>X Nipple - 03<br>Elbow - 1<br>Stator , Reeling . | 36 | 72 | Dwarakanagara 3rd cross |  |
| 5/10/19 | 03 | 7.5HP | Motor winding ,<br>base<br>bearing set<br>Stator , Reding .<br>NR·V - 1<br>X Nipple - 2<br>Union - 1<br>Reducer - 1<br>Union : 1<br>X . Nipple - 2 | Roll Pipe |  | Noor Nagara Main Road |  |

| Date | SL.NO | HP | Materials | PIPE | Thirdly<br>PIPE | Place | Signature |
|---|---|---|---|---|---|---|---|
| 8/10/19 | 04 | 15HP | Motor winding.<br>bush.<br>Test bearing.<br>Carbon Hadeling.<br>PUMP steel bush 20<br>Emplows - 20<br>PUMP blowers - 10<br>Poler. - 1 | 46 | | Kathigenahalli Hunchhaura Lay out | |
| 9/10/19 | 05 | 17.5HP | Motor winding.<br>bush<br>NRV - 1<br>Union - 1<br>X nipple = 03<br>Elbow - 02<br>Stater - 1<br>Relay - 1<br>Privender - 1 | 58 | | baba Nagara SLV Appartment | |
| 11/10/19 | 06 | 12.5HP | Motor winding<br>bush<br>Union.<br>X Nipple<br>NRV - 1<br>Collers - 2<br>Stater Relay<br>Privender.<br>Rotors - 1 | 37 | FA | Dalla Layout 1st cross | |

| Date | SL.NO | HP | Materials | PIPe. | Thridin<br>PIPE | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 12/10/19 | 07 | 15HP | Motor winding<br>bush<br>Test berny set<br>Carbon Housing .<br>stuter, Relay .<br>PUMP . Stell buse<br>sleves . 10<br>Rodor - 1 . | 54 | 108 | Baba Nagara | |
| 14/10/19 | (08) | 12·5HP | Motor winding<br>buse<br>Bering set<br>Privinder .<br>Stuter - Relay .<br>Cantact<br>NRV - 1<br>Union . 1 | 35 | 7 | Kogulu 4th Cross | |
| 15/10/19 | 09 | 12·5HP | Motor winding<br>buse<br>Soft - 1<br>Union . 1<br>X nipple - 2<br>callers - 2<br>Pump . sleved<br>. buse<br>Exeplears - 0.2<br>Stuter Privender | 37 | 74 | Thirumenahalli Main Raod | |

| Date | SL.NO | HP | Materials | Pipe | Threading Pipe | Place | Singarature |
|---|---|---|---|---|---|---|---|
| 18/10/19 | 10 | 12.5HP | Motor winding.<br>bush.<br>Bearing Set<br>stater.<br>Privender.<br>Relay.<br>Caller - 03<br>Foter - 1<br>NRV - 1 | 40 | 80 | Agrahara Layout 12th cross | |
| 20/10/19 | 11 | 17.5HP | Motor winding<br>Bush -<br>Emplewn - 10<br>bush - 20<br>blowers - 03<br>X. nipple - 02 | 48 | 96 | Kattigenahalli Sapthagiri lay out | |
| 21/10/19 | 12 | 17.5HP | Motor winding.<br>bering set<br>Pump stell bush<br>sleeve - 10<br>Empleaux - 02<br>Caller - 2<br>Union - 1 | 50 | | Dwarakanagara Balaji Layout | |
| 23/10/19 | 13 | 7.5HP | Moter. winding.<br>bering set<br>stater Relay.<br>Privinder<br>Union,<br>NRV - 1 | 12 | 12 | Bellahalli cross Main Road | |

1/011/19

Thridiy

| Date | SL.NO | HP | Materialer | APe | PIPE | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 3/11/19 | 01 | 17.5HP | Motor winding<br>berring set<br>buse<br>Soft 01<br>Stater, Relay.<br>Privender.<br>Contact 02<br>NRV - 1<br>union - 1 | 49 |  | Siri Nagara 2nd Cross |  |
| 7/11/19 | 02 | 15 HP | Motor winding.<br>berring set<br>buse<br>PUMP. Sleve<br>PUMP. buse<br>Empleard 03<br>X. Nipple - 02 | 45 | 90 | Basavalingappa Nagara (Balaji Ley out) |  |
| 9/11/19 | 03 | 15.HP | Motor winding<br>Test berring set<br>buse<br>PUMP. Sleve<br>. buse<br>Union. 01<br>NRV - 1<br>caller. | 45 | 45 | Defance colony Aganvdi Scchu |  |
| 14/11/19 | 04 | 15.HP | Motor winding.<br>buse<br>Stater Relay<br>prevender<br>Contactar. 02 | 45 | 90 | Dwarakanagara 1st |  |

| Date | SL.NO | HP. | Materailes | Pipe | Thriding Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 17/11/19 | 05 | 10 HP | Motor winding.<br>bushe<br>bering set<br>Soft<br>Stater Relay,<br>contact<br>NRV- 01<br>Union- 01 | 22 | | Chokkanahalli (gondu Thop) | ✓ |
| 19/11/19 | 06 | 15HP | Motor winding.<br>bushe<br>bering set<br>pump. bushe<br>pump. Empleans,<br>Sleves;<br>Caller.<br>Union. | 48 | | Agrahara layout 1st Main 11th cross | ✓ |
| 22/11/19 | 07 | 15 HP | Motor winding.<br>bushe<br>bering. set<br>Soft.<br>Stater. Relay,<br>contact<br>NRV- 01<br>Union- 01 | 50 | 100 | Balasu layout 2nd cross<br>Agrahara Layout | ✓ |
| 23/11/19 | 08 | 5HP | Motor winding<br>bushe<br>bering set<br>pump bushe<br>Stator, Relay | 9 | | Thirumenahalli 2nd Cross | |

Thridday

| Dat | SL.NO | HP | Materiales | Pipe | Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 25/11/19 | 09 | 5 HP | Motor winding.<br>bute<br>bearing Set<br>PUMP.<br>Impolyer – 05<br>Stell bush – 15<br>bowler – 02<br>Soft – 01<br>NRV – 1 | 08 |  | Pakanahalli Lake Near |  |
| 27/11/19 | 10. | 15 HP | Motor winding.<br>Bush<br>Set bearing.<br>Carbon Housing.<br>Stater.<br>Prevender.<br>Relay.<br>Contact no. 2<br>union.<br>NRV = 1<br>Callert – 2<br>X nipple – 03 | 45 | 90 | Defence Colony. Raja Kaluve Near. |  |
| 28/11/19 | 11 |  | Motor winding.<br>bute<br>Soft 01<br>Stater<br>Stater Relay.<br>PUMP. Selcet.<br>Emplemn – 2<br>PUMP. bute – 10<br>X Nipple – 2<br>Union – 1 | 08 |  | Agrahara Chamundi Layout |  |

1/12/19

Thriduty

| Date | Sl.No | HP | Materiales | PIPe | pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 1/12/19 | 01 | 15 HP | Motor winding.<br>buse<br>Test bering set<br>Stater.<br>Starter Relay.<br>PUMP.,<br>pump. sleves,<br>Emplaent - 05<br>PUMP ~~[illegible]~~ Buse - 10<br>Xnipple - 02 | 45 | 90 | Pelenahalli kalayanam | |
| 3/12/19 | 02 | | Motor winding.<br>Bush<br>Bearing set<br>PUMP.<br>Steel bush - 20<br>Bowlers. - 15<br>NR.V - 01<br>Union - 01<br>CIA. Elbow = 02 | 48 | | Ansandri layout (kallige nahalli) | |
| 6/12/19 | 03 | 15HP | Motor winding.<br>Motor buse<br>Flat bering set<br>PUMP. Soft<br>Empleants - 02<br>Sleve - 5<br>PUMP Buse - 10<br>Xnipple - 03<br>union - 1<br>Elbow - 2<br>coller - 2 | 44 | | Srinivaspura Smashana Near | |

| Date | SL.NO | HP | Materiales | PIPE | Thriding PIPE | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 5/12/19 | 04 | 17.5 HP | Motor winding<br>Test bering Seal<br>carbon bush<br>PUMP sleves<br>EMPlead - 05<br>steel buse - 20<br>Stater<br>stater Relay<br>Contact<br>Soft PUMP<br>Union | 42 |  | Vinayakanagara 1St Main |  |
| 9/12/19 | 05 | 15 HP | Motor winding<br>bush<br>carbon bush<br>pump - sleevel<br>Emplam - 05<br>steel buse - 20<br>Stater<br>Stater - Relay | 40 |  | Agrahara layout 7th cross |  |
| 13/12/19 | 06 | 12.5 HP | Motor winding<br>bush<br>carbon bush<br>pump . sleves<br>Stater<br>Soft<br>NRV - 1<br>Union . 1<br>x nipple - 3<br>collar - 2 | 33 | 66 | Vinayakanagar 2nd Main<br>Bellary Road. |  |

| Date | SL NO | HP | Materials | PIPe | Thrinding<br>PIPe | Place | Singanture |
|---|---|---|---|---|---|---|---|
| 15/12/19 | 07 | 10 HP | Motor winding.<br>buse<br>Tent berring set<br>Soft<br>stater.<br>Stater Peeling<br>Contact<br>Pump. Sleeve.<br>Pump EMPleard =03<br>buse - 10<br>X Nipple - 2 | 25 | | Mueneshwar Temple<br>Kutligenahalli | |
| 18/12/19 | 08 | 17.5 HP | Motor winding.<br>bering. Set<br>Carbon Housing Set<br>bush<br>Stater.<br>Privender.<br>Contact<br>Caller. 2<br>X Nipple - 2<br>NRV - 1<br>Union. - 1 | 47 | 47 | Umayukanagara PumpBack<br>Temple Road | 20-12-19 |
| 20/12/19 | 09 | 15 HP | Motor winding.<br>buse<br>Test bering. Set<br>Pump.<br>Pump. Sleve - 10<br>bush. - 20<br>EMPleard - 04<br>Elbow - 2 | 40 | | Dwarakanagara Over Tank | |

| | | | | | Thriduy | | |
|---|---|---|---|---|---|---|---|
| Date | SL.NO | HP | Materialles | Pipe | Pipe | Place | Singnature |
| 25/12/19 | 10 | 15 HP | Motor winding bore<br>Test berring set<br>Stater.<br>Stater Relay.<br>Condact<br>Privender.<br>Union . 1<br>Caller . 2<br>X Nipple 3<br>Union - 1 | 40 | | Balesi Lay out<br>Agrahara Lay out | |
| 27/12/19 | 11 | 17.5HP | Motor winding<br>Carbon Housing.<br>Pump.<br>Pump. Emloaves - 4<br>Steell bush - 10<br>Sleve - 20<br>Soft - 1<br>Union - 1 | 48 | 96 | Sri Ram Pura Temple Near. | |

Scanned by CamScanner

classmate
Date
Page

# 01/01/2020

| Date | SL.NO | HP | Materials | Pipe | Third<br>Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 1/01/20 | 01 | 15 HP | Motor winding<br>Test bering set<br>Carbon Housing<br>bush<br>Stater.<br>Stater Relay.<br>Privender<br>Contact 2<br>Caller - 2<br>X Nipple 2<br>union - 1 | 40 | | Agrahara Layout 8th cross | |
| 3/01/20 | 02 | 15HP | Motor winding<br>bering set<br>bush<br>PUMP.<br>PUMP Empleard - 10<br>Bush - 20<br>Sleven - 10<br>Stater<br>Stater privender.<br>Relay. | 43 | 86 | Kogilu Lay out Agrahara School Near. | |
| 6/01/20 | 03 | 12.5HP | Motor winding<br>bering set<br>bush<br>Stater.<br>Stater Relay.<br>Privender.<br>Culbert - 2<br>union - 1<br>NRV - 1<br>X Nipple - 2 | 50 | 100 | TIPP Nagar. Masidi Back Said | |

| Date | SL.NO | HP | Materials | Pipe | Threading<br>Pipe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 8/01/20 | 04 | 15 HP | Motor winding<br>bush<br>Test bering set<br>Corbon Housing<br>PUMP . Emplears -5<br>Bush -.10<br>Elbow - 2<br>X Nipple - 2<br>Union - 2<br>NRV - 1 | 44 | | Ayyuheera layout<br>9th cross | |
| 11/01/20 | 05 | 12.5 HP. | Motor winding.<br>bush<br>Stater.<br>Stater Relay<br>Privender<br>Contact<br>Union . 1<br>Callerd - 2<br>NRV - 1 | 35. | | Basavalingappanagara<br>Temple Near (10 mane<br>Road Near) | |
| 13/01/20 | 06 | 15 HP. | Motor winding<br>bush<br>Test bering set<br>PUMP. Soft<br>PUMP . IMpleams = 5<br>bule = 10<br>Sleve = 10<br>union = 1<br>X nipple -2<br>NRV - 1 | 37 | 74. | Kogilu layout Venkateshwara<br>Temple Near Road | |

| Date | SL NO | HP | Materials | PIPE | Thrding<br>PiPe | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 15/01/20 | 07 | 15HP. | Motor winding<br>Bush<br>Test bering set<br>Carbon Hauleing<br>stater Reley.<br>Stater contact<br>Privinder.<br>X nipple - 2<br>Union. 1 | 45 | | Basavalinga nagar.<br>Police Quarters Near<br>Road. | |
| 18/01/20 | 08 | 15HP. | Motor winding<br>bush<br>bering set<br>Rotor.<br>PUMP. EMpleams - 5<br>PUMP sleves - 10<br>bush - 20<br>NRV - 1<br>Union 1<br>Caller 2 | 45 | | Srinivas Pura [illegible]<br>Hemanna Temple Near | |
| 21/01/20 | 09 | 15HP | Motor winding<br>Test bering. set<br>Carbon House.<br>Stater<br>Stater Reley.<br>Privender<br>Contact<br>X nipple<br>NRV - 1<br>Union - 1<br>caller - 1 | 50 | | kalliganahalli Masidi<br>Road OH Circle Near | |

classmate
Date
Page

| Date | SL.NO | HP | Materials | Pipe | Thrduty<br>PIPE | Place | Singnature |
|---|---|---|---|---|---|---|---|
| 25/01/20 | 10 | 15HP. | Motor winding bush<br>Carbon Hawerry<br>Rotter.<br>Stater. Relay.<br>Privender<br>Contact<br>NRV - 1<br>Union.<br>X Nipple | 45 | 90 | Dwarakanagara brithavasa Collage Near. |  |
| 27/01/20 | 11 | 12.5HP | Moter winding bush.<br>PUMP. EMpleant. - 05<br>sleve - 10<br>bush = 20<br>Soft - 1<br>union - 1<br>culler - 2<br>Elbow - 3 | 35 | 35 | Air Force Compund Near. Dwarakanagara |  |